

**ACTON •
MICKELSON •
ENVIRONMENTAL, INC.**

LOG OF BORING

Facility: G-P Fort Bragg

Address: 90 W. Redwood Ave.
Fort Bragg, CA

MW-5.12

5175 Hillsdale Circle #100
El Dorado Hills, CA 95762

AME Project No.: 16017.08

Area No./ Description: Parcel 5, Mobil Equipment Shop (North)

Page 1 of 1

Drilling Company: RSI
Drilled By: Don Jenkins
Drilling Method: Hollow Stem
Boring Diameter: 8"
Sampling Method: California Modified Split Spoon Sampler
and Standard Penetration Test (SPT)

Location (East/North):
Ground Surface Elevation:
Water Depth (Date, Time): 3.5' (11/15/05 0825)
Casing Elevation:
Total Depth (feet): 19.5' BGS
Weather: clear/cool

Drilling Started: 11/15/05 0810
Drilling Finished: 11/15/05 0910

Logged By: J.D. Matthey, R.G., C.E.G
Checked By:

Source: Original field notes

PID/FID: PID

DEPTH (feet)	SAMPLE		BLOW COUNTS		SOIL DESCRIPTION SOIL NAME, COLOR, RELATIVE DENSITY OR CONSISTENCY, MOISTURE, PARTICLE SIZE RANGE, OTHER	GRAPHIC LOG	SOIL CLASS	WELL GRAPHIC	COMMENTS	FIELD PID READING (ppm)
	INTERVAL	SAMPLE ID	BLOWS/6 IN. (N)	IN. RECD/D					DRILLING RATE AND CONDITIONS, WATER DEPTH, BACKFILL	
0					ASPHALT.					
		MW-5.12-1.5	48-39-40 (79)	9	FILL - SILTY SAND (SM), light olive brown (2.5Y 5/3), Very Dense, Dry, 30% fine gravel, 0.5 cm clast, 50% fine to medium sand, 10% fines. Moist, Fill? light yellowish brown (2.5Y 6/3), Wet, 80% fine to medium sand, 20% fines.		SM		0825	0
5			2-9-9 (18)	12						
10			6-17-34 (51)	12						
15			9-15-20 (35)	14	Flowing Sands. Subrounded, Well Sorted, Massive, Rusy Mottles 80% fine sand, 20% fines.					
Boring Terminated Total Depth = 19.5'										

LOG OF BORING 1601708.GPJ ACTON.GDT 3/17/06